INDIAN ISTITUTE OF TECHNOLOGY (ISM), DHANBAD $\underline{\text{CAMPUS MAINTENANCE UNIT}}$

Dated: 05.06.2018

CORRIGENDUM

With reference to our NIT No. Maint/958027/18-19 dated 31.05.2018, SI. No. 07 may be read as.

| SI. | Description | Unit | Quantity | Rate | Amount |
|-----|---|------|----------|------|--------|
| 07 | Supply and installation of tower Airconditioner | TON | 50.00 | | |

Other terms & Conditions will be remain as same of earlier NIT.

Campus Engineer